TENNESSEE DEPARTMENT OF TRANSPORTATION **EROSION PREVENTION/SEDIMENT CONTROL** INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Page 1 of **6**

Reason For Inspection:

(1st Weekly)

2nd Weekly

											DATE: 12.3	5.//
State Route	(SR) / US Rou	ile or Road Na	me and De	scription:		1.	Are correcti	ve actions i	required by	this inspec	tion report (Y/N):	
		Wolfl	River Blvd.			NO, TOO WET TO WORK CONDITIONS						
County(ies):	· · · · · · · · · · · · · · · · · · ·	TDOT PIN:		NPDES Per	mit (NOC)	4 :	Number of I	New	Number of I	Recurring	Number of New	Number of Un-Corrected
Sh	elby	1016	15	Т	NR153299	ŀ	Corrective A	Actions:	Corrective A	Actions:	Sediment Releases:	Sediment Releases:
TDOT Gons 7994-	truction No.: 1535-54	TDOT Contra	ct No.:	Contractor: Acuff Enterprises Inc.			* 0,	W	* 2,	W		
prepared und designed to a information p	r penally of law er my direction o ssure that qualit resented. Based	or supervision ir lied personnel p d on my inquiry	n accordance roperly gath of the person	e with a syste ered and eva n or persons	m Ilualed who	COG EPSC	C Inspector a	and Tille (p			Signature:	Tandill
information, I of erosion an above I cert identified out	system, or those cerify that insped sediment contify that erosion a fall where installed	ections of storm rols have been and sediment co ed as planned a	waler discha performed a ontrols in the and designed	erge points (on single points) or conded in drainage are for the working of the condens of the c	ulfalls) and the table a of the			Tom Acuff	50 NO 1811-19	lype):	Signature:	
recorded in the table above. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment for knowing violations.					allies for sonment for	COG EPSC Project Manager (print or type): Timothy Bierdz				Signature:		
		TDOT EPSC	Inspectio	n Weekly R	lainfall Dat	a Log				A1000		
Dale	Day of Week	Predicted Precipitation (%)	Rainfall Gauge 1 (in)	Rainfall Gauge 2 (in)	Rainfall Gauge 3 (in)	Rainfall Gauge 4 (in)	Rainfall Gauge 5 (in)	Rainfall Gauge 6 (in)	Duration (hr)	TDOT/Contractor Agrees with Inspection Report: NO or YES If No, explain and initial:		
12.411	Sunday	50			N/A	N/A	N/A	N/A				
12-5-11	Monday	100	5.2	5.0	N/A	N/A	N/A	N/A	28			
12.6.11 12.7.11 12.8.11	Tuesday	30			N/A	N/A	N/A	N/A			And the second s	Annual Control of the
12-7.11	Wednesday	30			N/A	N/A	N/A	N/A				
12.8.11	Thursday	10			N/A	N/A	N/A	N/A			**************************************	
12.2.11	Friday	0			N/A	N/A	N/A	N/A				
12.3.11	Saturday	10			N/A	N/A	N/A	N/A				CONTRACTOR OF THE PROPERTY OF
	Sunday				N/A	N/A	N/A	N/A				
	Monday				N/A	N/A	N/A	N/A				
		Predicted Pre	ecipitation S	Source		www.we	alher.com			(Ad	dilional pages may b	e allached, if needed) Page 1 of 6

www.wealher.com

	· ÖFTI	IE ST	× .
6	-	Ž	13
	AGRIC	**	
1		1ERC 96 • 3	<i>\$</i> /.

State/US Route or Road Nam	е
----------------------------	---

Wolf Rive	r Blvd.
-----------	---------

70	OF.	1.35	27	-

TDOT Construction No.: 79954-3537-54 TDOT Contract No.:

CONDITION CODES

Date	12/5/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	12/1/2011		22,35	W	Weekly cleaning will be required, until further notice.
1A	1	21+50	RT	11/17/2011		41	W	RCBC Pedestrian Underpass/ No activity during this inspection.
1B	1	22+00	RT	11/10/2011		41	W	No activity during this inspection. Monitoring BMP's in place.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	W	Monitoring BMP's in place.
2A	1	33+50	LT,CL	12/1/2011		12,15,16,24	W	Monitoring BMP's in place.
2B	1	35+50	LT	12/1/2011		16,24	W	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	W	Monitoring BMP in place.
4	1	40+00	RT	11/7/2011	T = 10-24-11	15,16,43	I,RO,W	Repair wash out area. See 11-25-11 report for photo.
5A	1	49+00	RT	12/1/2011		16,33	W	Corrections made monitoring BMP's.
5B	1	50+00	RT	12/1/2011		9,16,33	W	Corrections made monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road		
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42 43	Bridge Construction Stream Realignment		
				40	Stream Neallyminem		

State/US I	Route or Road	Nam

Wolf River Blvd.

TDOT Construction No.: 7

79954-3537-54

TDOT Contract No.;

Date

12/5/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	12/1/2011		16,24,33	I,RO,W	Weekly cleaning for stream crossing required. A section of BMP's needs to be completed along top of north and south bank @ New Channel Realignment. See Photo.
6	1	56+00	LT	12/1/2011			W	Pond being drained during inspection. Currently Stable.
7	1	60+00	RT	10/24/2011		16, 33	w	Currently Stable, Monitoring BMP's.
8A	1	73+00	RT	12/1/2011		16,24,42	w	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	W	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	12/1/2011		16,35,42	W	Bridge construction zone. Monitoring BMP's.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	W	Bridge construction zone. Monitoring BMP's.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	W	Weekly watering required until seed establishes.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	W	Weekly watering required until seed establishes.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy, Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 **Brush Barrier** 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed Sediment Removal 6 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** 1 Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam 36 RO Repeat Occurrence 9 Sediment Trap / Basin Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

CONDITION CODES

State/US	Route o	r Road	Name
----------	---------	--------	------

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	12/5/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	W	Weekly watering required until seed establishes.
10A	2	85+00	RT	9/29/2011		15,16,35,41	w	Monitoring BMP's in place.
10B	2	85+00	RT	9/29/2011		15,16,35,41	w	Monitoring BMP's in place.
10C	2	85+50	LT	11/14/2011		15,16,35,41	w	Monitoring BMP's in place.
10D	2	84+50	LT	11/14/2011		15,16,35,41	w	Monitoring BMP's in place.
11A	2	92+50	RT	11/14/2011		35,41	w	Monitoring BMP's in place.
11B	2	92+50	LT	10/6/2011		10,32,35,41	w	Remove forms when accessible.
11C	2	92+00	LT	10/6/2011		10,32,35,41	w	Remove forms when accessible.
	1	11+28	LT	12/1/2011		19,35	w	Daily cleaning is required, until further notice.
	1	13+40	RT	12/1/2011		23,29,30	W	Daily cleaning will be required, until further notice.
	1	107+75 EROSIO I	CL N AND SEDIME	12/1/2011 NT CONTROL M	MEASURE CODES	23,29,30	W	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 31 Replacement Needed 3 Temporary Slope Drain 17 **Erosion Control Blanket** Ditch Liner R FM Future Maintenance Rock Check Dams 18 32 Rock Silt Screen Flexible Channel Liner Brush Barrier Temporary Silt Fence with Backing С Cleaning Needed 5 19 Catch Basin / Storm Inlet Protection 33 Enhanced Silt Fence 6 Sediment Removal 20 Riprap Outlet Structure 34 1 Increase Measures 7 Straw Bale Check 35 Sediment Tube W Too Wet to Work Conditions 21 Riprap Energy / Velocity Dissipater Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 8 SR Sediment Release 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues 10 Temp Sediment Filter Bag / Dewatering 24 **Temporary Stream Crossing** 38 Berm (soil, riprap, rock) FS Final Stabilized 25 39 S Stable (No Action Needed) 11 Polyethylene Sheeting Turbidity Barrier / Silt Boom Gabion Machined Rip Rap Other (O31): 26 Temporary Stream Diversion 40 Sheet Pilling 12 Haul Road Other (O#2): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3): 14

EPSC Inspection

Page 4 of 6

	OF THE ST	
18	APA 9	
	AGRICULTURE	-
1	1756 S	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	12/5/2011	

					Date of	Existing		
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
(Existing	No.	From / To			T = Temp.	Measure	Codes	
Structure)					P = Perm.	Codes*		
								Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	12/1/2011		19,22	W	notice.
		South side of						Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	12/1/2011		19,22	W	notice.
		North side of					12	Daily cleaning will be required, until further
* 12+80	1	WRB	LT	12/1/2011		19,22	W	notice.
		Walking Trail						
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	l w	Currently stable, Monitoring BMP's
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	w	Currently stable.
		Sta. 13+40 -						Haul roads dampened frequently for dust
		Sta. 107+75	LT, RT or CL	10/13/2011		30	w	control, until further notice.

	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	W	Weekly watering required until seed establishes.
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15 16 25	w	Mackburghering required until good actablished
		92+50 - 107+00	ЩЬІ	9/29/2011	1 - 10-03-11	15,16,35	VV	Weekly watering required until seed establishes.
	4	0.75		40/4/0044		40.00	100	Daily cleaning will be required, until further
	. 1	6+75	LT	12/1/2011		19,22	W	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	w	Currently stable, Monitoring BMP's
	1	34+00	RT	8/25/2011	T= 8-25-11	16	w	Currently stable, Monitoring BMP's
		EROSI	ON AND SEDIMEN	T CONTROL ME	ASURE CODES	200 Wes	입장 공화 공인	CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

	OFTH	E S	
16	29		1
EA.	AGRICU	TURE	
1/2	NAM.		/
7	17	6	

0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date _____12/5/2011

0.45-11.11	D .:		17.57		Date of	Existing		
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
	No.	From / To			T = Temp.	Measure	Codes*	
					P = Perm.	Codes*		100
	200		W. C.		2000	2000 00 - 9 ago (1000 Acrosti) - 2000		Weekly watering required until seed
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	W	establishes.
								Weekly watering required until seed
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	W	establishes.
	1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
			8					
***************************************	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
		21.00	17.1	10/0/2011	1 - 10-0-11	10, 10,00,00,41		Currently stable, monitoring bivir's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	W	Currently stable, monitoring BMP's.
								Currently stable, monitoring BMP's. Weekly
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	W	watering required until seed establishes.
	N	North side of						Daily cleaning will be required, until further
* 108+37		WRB	LT	12/1/2011		19,22	W	notice.
			12.525					
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	W	Currently stable, monitoring BMP's.
				354330000000000000000000000000000000000		areas areas feet		
	1952	No. of the second				V		

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 30 Haul Roads Dampened for Dust Control Temporary Mulch U Upgrade Needed (Failure Noted) Ditch Liner 3 Temporary Slope Drain 17 Erosion Control Blanket 31 R Replacement Needed **Rock Check Dams** 18 Flexible Channel Liner Rock Silt Screen 32 FM Future Maintenance Temporary Silt Fence with Backing Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):

CONDITION CODES